


# Fire Prevention Tips

## For Shop Areas

Never leave used rags laying around.

- Especially those that are soaked with oil, grease, lacquer thinner, gas, diesel, paint, or varnishes.
- Throw them away in approved steel oily waste cans.



Pay attention to your surroundings when doing any type of hot work.

- This involves : cutting, welding, using hand grinder, bench grinder, cutoff saw... anything involving sparks.
- Look for & move anything that could burn or blow up:  
Rags, papers, drain pans, auto batteries, aerosol cans
- Throw your sparks towards the floor.
- Have a fire extinguisher or water hose within 10'



No smoking

- go outside to designated areas



Keep all equipment, machinery, & vehicle leaks repaired.

- Fuel & fluid lines
- If you see or smell a problem check it out




When refueling, turn your vehicle/equipment off



Never use water on electrical or grease fires

- this could cause electrocution or make the fire spread
- only use ABC fire extinguishers



Good Housekeeping

- keep spills cleaned up
- don't let piles build up – sawdust (on electrical panels & receptacle boxes)
- trash & junk in general cleaned up

